IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

APPLICANT(S): Strater, et al

SERIAL NO.:

10/074,806

PATENT NO.:

7,450,561 B2

FILED:

February 13, 2002

ISSUED:

November 11, 2008

DOCKET NO.:

D02761

ENTITLED:

METHOD AND APPARATUS FOR RESERVING AND RELEASING

BANDWIDTH FOR A PACKET-SWITCHED TELEPHONY

CONNECTION ESTABLISHED OVER AN HFC CABLE NETWORK

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 CFR 1.323

ATTN: Certificate of Correction Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

In accordance with the provisions of 37 CFR 1.323 of the Rules of Practice which implement 35 U.S.C. 255, the Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

As stated in the attached Certificate of Correction Form (PTO/SB/44), the above identified patent has errors.

Applicant states that the errors occurred in good faith and are of a clerical or typographical nature, or of a minor character. The changes necessary to correct these errors in the patent would not constitute new matter and would not require re-examination. As such, Applicant requests the issuance of a Certificate of Correction.

Please charge Deposit Account 502117, Motorola, Inc., for the fee required by 37 C.F.R. 1.20(a). The Commissioner is further authorized to charge any additional fees that may be due, or credit any overpayment to Deposit Account 502117, Motorola, Inc.

Respectfully submitted,

Please forward all correspondence to:

Motorola, Inc. 101 Tournament Drive

Horsham, PA 19044

Customer No.: 43471

By: /Larry T. Cullen/

Larry T. Cullen

Attorney for Applicant Registration No. 44,489 Phone: 215-323-1797

Fax: 215-323-1300

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,450,561 B2	Page <u>1</u>	_ of1
APPLICATION NO.: 10/074,806		
ISSUE DATE : November 11, 2008		
INVENTOR(S) : Strater, et al		
It is certified that an error appears or errors appear in the above-identified patent and to is hereby corrected as shown below:	hat said Lette	rs Patent
FIGURE 4, Sheet 4 of 4, for Tag "410", Line 2, please delete "BANSWIDTH" and replace w	rithBANDWI	IDTH
COLUMN 3 Line 5: Please delete "1101," and replace with—110 ₁ ,		
COLUMN 6: Line 25: Please delete "MTAt," and replace with—MTA _t , Line 38: Please delete "MTAt" and replace with—MTA _t — Line 40: Please delete "MTAo." and replace with—MTA _o .— Line 65: Please delete "MTAt." and replace with—MTA _t .—		
COLUMN 7: Line 1: Please delete "MTAt" and replace with—MTA _t —Line 23: Please delete "MTAt" and replace with—MTA _t —		
COLUMN 8: Line 43: Please delete "Agent." and replace with—Agent		

MAILING ADDRESS OF SENDER (Please do not use customer number below):

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.